

Attachment C



CHAIN COMPANY A BORG WARNER INDUSTRY
HIGH QUALITY POWER TRANSMISSION EQUIPMENT SINCE 1893

ITHACA, NEW YORK
TELEPHONE 4-6471

April 19, 1963

Tompkins County Department of Health
1285 Trumansburg Road
Ithaca, New York

Re: Oil Seepage into Six Mile Creek

Attention: Mr. Frank R. Liguori,
Sanitary Engineer

Dear Mr. Liguori:

Per our discussion of Friday, April 12, three sealed prints of our Drawing #B-118586 are attached and hereby submitted for your examination and approval as the means to collect oil at our scrap dock and thereby eliminate oil seepage into the South Cayuga Street storm drain and subsequent contamination of Six Mile Creek.


We estimate approximately 300 gallons/day of oil waste to be collected. Under normal conditions, the second compartment of the separation-collection tank will not become full and all compartments will be emptied on a periodic basis by industrial waste oil collection tank truck. The addition of surface water entering the system will have the effect of increased rate of filling the second compartment. Estimated surface water collection is 2,000 gallons for a 1" rain fall.

Please advise if additional information is required. We will be preparing a separate drawing of the two compartment tank, but detailed only to the extent to give sufficient dimensions for fabrication by our own fabricators.

Incidentally, oil seepage has practically stopped at this time as a result of the first phase of work in this program.

Very truly yours,

MORSE CHAIN COMPANY


A. L. Ferrel,
Plant Engineer

ALF/cb